1.) The leak detection and frost patrols are done per 49 CFR 192.723 and 192.721. Regulator station inspections are done by Columbia Gas and valve inspections are done twice a year.
2.) Our two employees rely on their conbined experience of 80 years in the gas field working for Hanley and Bird (Exco) and National fuel.
3.) This is covered in our Emergency Response section of our O &M Manuel Section 5 page 1.
4.) We hold back 3 to 4 well to manage peak days.
5.) 48 customers
6.) No outages or pressure issues occurred January 1st through January 31st 2014