BEFORE THE PENSYLVANIA PUBLIC UTILITY COMMISSION Harrisburg, PA 17105-3265

In re: Sunoco Pipeline L.P. a/k/a

Energy Transfer Partners

Docket No. P-2018-3000281

Petition of the Bureau of Investigation And Enforcement of the Pennsylvania Public Utility Commission for the

Public Utility Commission for the Issuance of an *Ex Parte* Emergency

Order

PETITION FOR INTERVENTION PURSUANT TO 52 Pa. CODE CHAPTER 5A

AND NOW, this <u>25</u> day of March, 2018, comes Mitch Trembicki, residing at 187 Middletown Road, Glen Mills PA 19342 in Thornbury Township, Delaware County, seeking to intervene as a party in the above-captioned matter and, in support thereof, avers as follows:

- (1) On March 7, 2018 the Bureau of Investigation and Enforcement (BIE) of the Pennsylvania Public Utility Commission (Commission) filed a Petition for Issuance of an *Ex Parte* Emergency Order to the above referenced Docket seeking emergency relief against Sunoco Pipeline L.P. (Sunoco) pursuant to 52 Pa. Code 3.1-3.4.
- (2) The factual circumstances that underlay the BIE's Petition for Emergency Relief included initial communications by affected landowners including Petitioners herein to which the BIE responded and found a series of sinkholes near properties located on Lisa Drive in West Whiteland Township, Chester County, Pennsylvania.
- (3) The sinkholes found by the BIE presented and continue to present a clear, present, significant, imminent danger to the affected property owners including Petitioners herein because they had undermined and are continuing to undermine and leave unsupported and are in the immediate vicinity of a pipeline constructed in the 1930s and recently repurposed by Sunoco to transport highly volatile, potentially explosive natural gas liquids (NGL) from Ohio and western Pennsylvania to the Sunoco export facility now known as the Marcus Hook Industrial Complex located in Pennsylvania and Delaware. This operating pipeline is known and referred to herein as Mariner East 1 (ME1) and was at the time of the sinkhole formation and is (on information and belief) currently transporting these hazardous, highly volatile NGLs.

¹ The residence at 187 Middletown Road, Glen Mills PA 19342 is approximately 180 feet from Mariner East 1.

- (4) The hazardous, highly volatile liquid NGLs being transported by ME1, if released to the atmosphere for any reason, change phase to odorless, colorless, heavier-than-air gas which is extremely flammable, potentially explosive, and asphyxiating. These materials therefore, present a clear, imminent and existential hazard to persons that reside, work, or travel in proximity to ME1, including Petitioner herein.
- (5) The BIE also found and Petitioner here avers that Sunoco's on-site agents contracted to have large quantities of flowable fill deposited in each of the sinkholes:
 - (a) without a permit to do so or notifying any jurisdictional regulatory agency,
 - (b) without consultation with any geologist or expert on sinkhole remediation,
 - (c) without creating any sinkhole remediation plan,
 - (d) without studying or mapping surface or ground water flows,
 - (e) without conducting any studies or testing of the underlying geology by resistivity, seismic investigation, ground penetrating radar or otherwise,
 - (f) without excavating the sinkhole openings to bedrock,
 - (g) without pressure grouting any underground voids,
 - (h) without constructing any plug or bridge to prevent further sinkhole collapse;
- (i) without relocating, providing any additional support to or means to prevent strain by weighting, floatation or otherwise either the operating pipeline (ME1) or the two additional pipelines currently being constructed by Sunoco in close proximity within the same easement as ME1 and known and referred to herein as ME2 and ME2X.
- (6) Petitioner avers on information and belief that some or all of the listed actions in subparagraphs (a)-(i) of paragraph (5) above were necessary to protect the lives, health, safety, and property of Petitioner.
- (7) Petitioner avers on information and belief that the deposition by Sunoco of this flowable fill was not an appropriate method to safely remediate the sinkholes or to protect the ME1, ME2 or ME2X pipelines from further or future damage including catastrophic failure.

- (8) Petitioner avers on information and belief that the deposition of this flowable fill by Sunoco was completed in an attempt to camouflage the extent of the sinkhole activity and its relationship to the ME1, ME2 and ME2X pipelines from neighboring property owners, local officials, and regulatory personnel.
- (9) As BIE averred in its Petition for *Ex Parte* emergency relief, Sunoco's actions have left the integrity of ME1 "potentially hazardous to life, property, and the environment." Petition for *Ex Parte* Relief at page 1. The lives and property referred to include that of Petitioner herein.
- (10) By Order dated and entered on March 7, 2018, the Commission granted BIE's Petition for Emergency *Ex Parte* Relief requiring Sunoco to accomplish, *inter alia*, "at least one in line inspection tool" run through ME1 from one mile to the north to one mile to the south of Lisa Drive; thereafter to suspend hazardous liquid flow while maintaining pressure of 475 to 650 psig in ME1 for a 10-14 day study period, geophysical testing in the ME1 Horizontal Direct Drilling (HDD) area; and to discuss with BIE and Pipeline Safety staff the addition of strain gauges to ME1 "in the study area".
- (11) Neither BIE's Petition nor the Emergency Order make any direct reference to further study, proper design and preparation by suitable experts, or implementation of proper sinkhole remediation.
- (12) Neither BIE's Petition nor the Emergency Order make any direct reference to the lives, health, safety, or property of neighboring property owners including Petitioner herein during the study period as it may be extended or thereafter in the event that ME1 operation and/or ME2 and ME2X construction and operation continue without proper sinkhole remediation.
- (13) No provision has been made to protect Petitioner's life, health, safety, or property during the operation of ME1 or the construction and operation of ME2 or ME2X now being constructed without pause in the same geologically unstable area as caused the emergency situation with ME1.
- (14) Petitioner is eligible to intervene in this matter pursuant to 52 Pa. Code 5.72 because, *inter alia*:
 - (a) Petitioner is asserting rights guaranteed by the United States and Commonwealth of Pennsylvania Constitutions including without limitation the rights to due process before the deprivation of life, liberty, or property protected by the Takings Clause of the Fifth Amendment applicable to the states by force of the Fourteenth Amendment of the United States Constitution; the right to enjoy and defend life, liberty, and property protected by Article I, Section 1 of the Constitution of the Commonwealth of Pennsylvania, and the right of the people under the

Environmental Rights Amendment of Article I, Section 27 of the Constitution of the Commonwealth of Pennsylvania;

- (b) Petitioner is asserting interests which may be directly affected by this matter but which are not adequately presented by existing participants including but not limited to the interests recited in paragraphs (6) through (9) above; subsection (a) of this paragraph, and the interests described in paragraphs (11) through (13) of this Petition; and
- (c) It is in the interest of the public that Petitioner participates by intervention in this matter to ensure that the parties do not, by agreement or otherwise, limit or fail to undertake or to require and inspect in a workmanlike, good faith manner any of the protective actions required by the Emergency Order or discovered during the study period to be necessary to protect the public including Petitioners herein or to fail to address by adequate means the concerns described by reference in the preceding subsection (b) of this paragraph.

Public Safety Concerns

- (15) Between 2006-2018, Sunoco reported to the federal government that it experienced 295 hazardous liquids pipeline leaks (*see* Attachment C).
- (16) On information and belief, Sunoco has demonstrated an inability to reliably detect leaks in its pipeline systems. For example: Sweetwater TX, 2016 (12 days between initial control room indications that a leak was underway and its confirmation); Tinicum, PA, 2000; Edgmont Township, PA, 1988, 1992 and 2015; Morgantown, PA, 2017 (third leak of highly volatile liquids from ME1 in less than one year).
- (17) On information and belief, Sunoco itself is unable to guarantee that ME1 will not experience additional leaks.
- (18) On information and belief, PUC is unable to guarantee that ME1 will not experience further leaks.
- (19) On information and belief, Sunoco itself acknowledges that even small leaks of NGLs can have very serious consequences.
- (20) On information and belief, if further leaks occur on ME1, it is possible that substantially the entire contents of the segment between block valves will volatilize and become released to the atmosphere, even if the block valves were to close instantly.
- (21) On information and belief, Sunoco has in fact reported to PHMSA three separate leaks of NGLs from ME1 during 2016-2017. One of these leaks involved a

failure of the pipeline itself, while two occurred on new, above ground equipment. Sunoco failed to detect that one of these leaks was occurring, and all of them occurred in high consequence areas.

- (22) NGLs, if released to the atmosphere, volatilize to gas which is colorless, odorless, heavier than air, and extremely flammable.
- (23) Past delayed-ignition accidents involving highly volatile liquids have caused fatalities, injuries and property damage over large areas. See NTSB accident reports for Franklin County, MO; Puerto Rico, San Juan; Brenham, TX; Blenheim, NY.
- (24) Despite making numerous requests over a period of years for a credible notification system and evacuation guidance, neither Thornbury Township nor area residents have been provided either. The guidance provided (on-foot self-evacuation in the correct upwind or uphill direction) is not credibly possible for many residents in proximity to ME1, particularly at night or during inclement weather.
- (25) In the event that the Commission grants the instant Petition to Intervene, Petitioner intends to support the actions of BIE and the PHMSA Office of Pipeline Safety to ensure that the protections described in the Emergency Order of March 7, 2018 are implemented fully and in good faith; assert and defend the interests described in paragraph (14) above and further support the interests of the neighbors and the affected public including stakeholders (such as elementary schools) in high consequence areas (HCA) along the route of ME1, and proposed route of ME2 and ME2X in the proper resolution and remediation of the public hazards made the subject of BIE's Emergency Petition for *Ex Part*e Relief and the Commission's responsive Emergency Order dated March 7, 2018.

NOW, THEREFORE, on the basis of the averments set forth above the Petitioner respectfully requests the Commission enter an Order granting the instant Petition for Intervention pursuant to 52 Pa. Code 5.75; order the production of a publicly available plan for the notification and self-evacuation of the public as described in the letter from Thornbury Township, Delaware County to Sunoco dated August 29, 2016 (see Exhibit A) and Thornbury Township Proclamation of Concern dated September 21, 2016 (see Exhibit B); and any related relief the Commission deems appropriate.

	Respectfully submitted,
Mitch Thu	nlishi"
Mitch TR	EMBICKI

VERIFICATION

facts averred in this Petition for Inte- knowledge, information, and belief.	Petitioner herein, hereby state that the ervention are true and correct to the best of my I understand that the statements herein are
authorities.	Pa. C.S. 4904 relating to unsworn falsification to
3-75-14	
<u>3-25-18</u> Date	
	Mitch Tumbichi
	MITCH TREMBICKI

Pennsylvania Public Utility Commission

In re: Sunoco Pipeline L.P. a/k/a

Energy Transfer Partners

Docket No. P-2018-3000281

Petition of the Bureau of Investigation And Enforcement of the Pennsylvania Public Utility Commission for the Issuance of an *Ex Parte* Emergency Order

Petitioner

V.

Sunoco Pipeline L.P. a/k/a/ Energy Transfer Partners,

Respondent

CERTIFICATE OF SERVICE OF PETITION TO INTERVENE

I, Mitch Trembicki, hereby certify that I have on March 26, 2018 filed and served a true and correct copy of the foregoing Petition to Intervene upon the Commission and the parties listed below at the addresses set forth below in accordance with the requirements of 52 Pa. Code 1.54.

Filing of Original Process (via e-filing):

Rosemary Chiavetta, Secretary Pennsylvania Public Utility Commission P.O. Box 3265 Harrisburg PA 17105-3265

Service by First Class Mail:

Paul Metro Fixed Utility Valuation Manager, Bureau of Investigation and Enforcement Safety Division; and


Michael L. Swindler, Esquire **Deputy Chief Prosecutor** Pennsylvania Public Utility Commission P.O. Box 3265 Harrisburg PA 17105-3265

Curtis Stambaugh, Esquire Assistant General Counsel Sunoco Logistics Partners L.P. 212 3rd Street, Suite 201 Harrisburg PA 17101

Nels Taber, Esquire Senior Litigation Counsel Department of Environmental Protection Office of Chief Counsel 400 Market Street, 9th Floor Harrisburg PA 17101

Robert Burroughs PHMSA Eastern Region 820 Bear Tavern Road, Suite 103 West Trenton NJ 08628

Office of the Consumer Advocate 555 Walnut Street 5th Floor, Forum Place Harrisburg PA 17101-1923





THORNBURY W W W . T H O R N B U R Y . O R G

BOARD OF SUPERVISORS:

James H. Raith James P. Kelly Sheri L. Perkins

Public Meeting: 1st Wednesday of each month

August 29, 2016

Sunoco Logistics Sunoco Pipeline L.P. 525 Fritztown Road Sinking Spring, PA

Re: Mariner East 2 Pipeline Project
Thornbury Township, Delaware County, Pennsylvania

Dear Sir/Madam,

The Board of Supervisors of Thornbury Township requests that Sunoco Logistics address concerns outlined in this correspondence prior to the start of any construction activity associated with the proposed Mariner 2 East pipeline project within our township.

As your due diligence may have revealed, many township residences in the area of the proposed pipeline are served by on-site wells. The township and its residents are concerned that the activity associated with the construction of the project, as well as the on-going operation of the project, may have a negative impact on the natural groundwater systems which provide drinking water to residents. We would like to provide our residents with your written plan and procedures for ensuring the integrity of the existing on-site water systems is maintained.

Our understanding is that proposed construction methods may create voids between the proposed pipeline and surrounding earth and that it is Sunoco's intention to leave those voids open and unfilled, thus creating a potential pathway for groundwater contamination. The township believes it would be appropriate for Sunoco's construction methods to include grouting those voids. Additionally, we request that Sunoco establish a benchmark of the condition and quality of each of the wells within a prescribed radius along the project and monitor those same wells for an acceptable period of time post-construction to ensure no degradation of the groundwater.

In addition, given a recent leak in neighboring Edgmont Township, which involved the transmission of a far less volatile product, Thornbury is requesting that shutoff valves be installed in the pipeline preceding the township boundary where the project enters, as well as at the boundary where the project exits Thornbury Township. This would provide an additional level of safety for both our residential and commercial property owners whose properties would be most immediately and severely impacted by a breach of the pipeline. It would also provide Sunoco with the ability to respond quickly to an emergency, mitigating possible damage.

Finally and perhaps most importantly, our Board of Supervisors has concerns over the safety record of Sunoco as presented by the Pipeline and Hazardous Material Safely Administration. We request a meeting to identify potential threats during construction and operation of the project to ensure that a viable evacuation plan is established in the event of any emergency. We would also like to meet to discuss any other safeguards appropriate to best protect our residents and their property.


If the project moves forward, the township may have additional questions and concerns to be addressed; however given the importance of those stated above we thought it would be best to have these issues addressed first. We look forward to hearing from you regarding the foregoing as soon as possible.

Sincerely,

James H<mark>. R</mark>aith

Chairman

Board of Supervisors
Thornbury Township



THORNBURY TOWNSHIP DELAWARE COUNTY, PENNSYLVANIA

PROCLAMATION

A PROCLAMATION of the Board of Supervisors of Thornbury Township, Delaware County, Pennsylvania, expressing great concern to the Governor of the Commonwealth of Pennsylvania and to the Pennsylvania Department of Environmental Protection (PADEP) regarding hazardous liquids transmission pipeline projects that increase the risk of catastrophic accidents and jeopardize the health, safety and welfare of Township residents, especially when such projects provide no corresponding benefit within the Township.

WHEREAS, Sunoco Pipeline L.P. (Sunoco) has announced that it is currently transporting highly volatile liquids under pressure through Thornbury Township, a "high consequence area," using a repurposed transmission pipeline installed in the 1960s with a capacity of 70,000 barrels (2,940,000 gallons) per day (Mariner East 1); and

WHEREAS, an additional proposed Sunoco pipeline known as Mariner East 2 could, if constructed, transport through Thornbury Township an additional 275,000 barrels (11,550,000 gallons) per day of these same materials (with the potential to expand to 450,000 barrels (18,900,000 gallons) per day); and

WHEREAS, the highly volatile liquids, which are being transported through the Township for the first time by Sunoco, are, if released, gaseous, invisible, odorless, toxic, heavier than air and highly flammable; and

WHEREAS, this project has the potential to jeopardize public safety in Thornbury Township by accidental leaks, explosions, or fire; and

WHEREAS, the highly volatile liquids which Sunoco is transporting and proposes to transport through Thornbury Township are overwhelmingly intended for export to overseas markets and customers; and

WHEREAS, the transportation of these highly volatile liquids through Thornbury Township provides no direct benefit to either the municipality or its residents; and

WHEREAS, Sunoco has at least 263 reported hazardous liquid spills since 2006, according to records maintained by the federal Pipeline and Hazardous Materials Safety Administration (PHMSA).

NOW THEREFORE, BE IT PROCLAIMED by the Board of Supervisors of Thornbury Township, Delaware County, that the Township expresses deep concern about the

existing and proposed Sunoco Mariner East transmission pipelines to the Governor of the Commonwealth and the Secretary of the Pennsylvania Department of Environmental Protection. Of particular concern to the Board of Supervisors are:

ı

The high level of risk to Township residents which may occur due to the nature of the highly volatile liquids being transported and proposed to be transported through the Township. This risk must be demonstrably mitigated by such measures as the development of an incident response plan which includes (but is not limited to) viable worst-case evacuation routes developed in cooperation with the Township personnel and affected residents; enhanced safety equipment and safety training for first responders; and separation of new pipelines from existing residences by a distance equal to or greater than the Potential Impact Radius (PIR) of those pipelines.

II

The inherent dangers of transporting highly volatile liquids under pressure through Thornbury Township, coupled with the fact that if released, these liquids are gaseous, invisible, odorless, toxic, heavier than air and highly flammable, requires that Sunoco have the ability to immediately stop the release once detected or reported. This risk can be demonstrably mitigated by the installation of shutoff valves both prior to the Township boundary where the transmission pipelines enter, as well as at the boundary where the transmission pipelines exit the Township. To the extent that release detection instruments can be provided to affected residents adjacent to a transmission pipeline, they should be provided and maintained by Sunoco with appropriate training provided to residents and Township personnel. This would afford an additional level of safety and notice for Township residents whose properties would be most immediately and severely impacted by a breach of the pipeline and provide Sunoco with the ability to more quickly respond to an emergency, hopefully avoiding the loss of persons and mitigating damage to property.

Ш

The Mariner East 2 project may threaten the private water supply of a number of Township residents as the proposed construction method has potential to create voids between the proposed pipeline and surrounding earth and that it is Sunoco's intention to leave these voids ungrouted, creating an unacceptable pathway for groundwater contamination. Proper and reasonable safeguard would be for Sunoco to establish a benchmark of the condition and quality of each of the wells within a prescribed radius along the project and monitor those same wells for an acceptable period of time post-construction to reasonably ensure no degradation of the groundwater.

The Mariner East 2 project construction will disturb and alter essential elements of thoughtfully approved subdivisions. Such disturbance will adversely affect safeguards both within and without those subdivisions which have been carefully implemented in the establishment of those subdivisions. Sunoco must be required to restore such conditions and safeguards to the condition which the same were in immediately prior to the commencement of any construction.

٧

To the extent that the Mariner East 2 project is approved by all necessary agencies with jurisdiction thereover, the Commonwealth must insure that such construction includes the simultaneous construction of both the proposed 20" pipeline and contemplated 16" additional pipeline, whether or not the such construction is deemed advisable or advantageous by Sunoco. To do otherwise will cause another significant period of hardship, consternation and anxiety to the residents of Township and surrounding community. This is a circumstance which is both unnecessary and easily avoided.

VI

Essential to the powers of the Township, are the police powers granted by the Second Class Township Code and the power to regulate the uses and development of land by the Pennsylvania Municipalities Planning Code. Exemptions given to public utilities under each of these enabling bodies of law severely weaken the Township's ability to exercise its police powers and its ability to fully protect the health, safety and welfare of its residents and are contrary to the Commonwealth's ongoing obligation under Article 1, Section 27 of the Constitution of the Commonwealth, which provides:

"The people have a right to clean air, pure water, and to the preservation of the natural, scenic, historic and esthetic values of the environment. Pennsylvania's public natural resources are the common property of all the people, including generations yet to come. As trustee of these resources, the Commonwealth shall conserve and maintain them for the benefit of all the people."

The consequences of such exemptions squarely favor commerce over community safety and are contrary to the preservation of the public trust created by the Commonwealth Constitution. Legislation is needed to more fully empower the Township to exercise control over public utility facilities at the local level, which in turn supports the Commonwealth's responsibility toward the citizens of the Commonwealth.

PROCLAIMED by the Board of Supervisors of Thornbury Township, Delaware County, Pennsylvania, at the regular meeting of said Board held this 21st day of September, 2016.

BOARD OF SUPERVISORS

Thornbury Township,

Delaware County, Pennsylvapia

James H. Raith, Chairman

J.P. Kelly, Vice Chairman


Sheri L. Perkins, Supervisor

Attest:

Geoffrey Carbutt, Secretary

(TOWNSHIP SEAL)

NIEDSISSIDOCS1013001100053119N7565.DOCX



Operator Information

Incident and Mileage Data

SUNOCO PIPELINE L.P.

(Operator ID:18718 - CURRENTLY ACTIVE OPID)

Main Operator Report Page - Incidents and Mileage - Federal Inspection and Enforcement Data - More Pipeline Operators

The reports below provide mileage data based on this operator's latest submissions to PHMSA, as well as their incident data since 2006.

The data sources for the mileages in this report are the Annual Report for Gas Distribution, Gas Transmission and Hazardous Liquid (1) mileages. All mileages are for in-service pipelines and reflect data submitted to PHMSA by this operator.

The data sources for the incidents in this report are the PHMSA Flagged Incident Files⁽²⁾. Where appropriate, the table columns can be sorted by clicking the corresponding column header.

eline Mi	ileage Ov	verview Incidents	Milea	ge by Commodit	y Mileage by State								
l Pipelin	ne System	ns Hazardous Liq	uid Syst	ems Gas Trans	smission Systems Detail								
ious Inci	idents are	denoted in red.											
	PIPELIN												
l Incide	ents(2): 20	006-2018											
Date	System	City	State	County	Cause	Sub Cause	Fatalities	Injuries	Property Damage (A)	Gross Barrels Spilled (Haz Liq)	Net Barrels Lost (Haz Liq) (B)(C)	Value of Product Lost ^(D)	
/15/18	HL	SINKING SPRING	PA	BERKS	NATURAL FORCE DAMAGE	TEMPERATURE	0	0	\$2,350	2	0	\$250	
/27/17	HL	WILLARD	ОН	HURON	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT	0	0	\$3,185	0	0	\$35	
01/17	HL	ST. CLAIR	MI	ST. CLAIR	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT	0	0	\$45,877	1	0	\$27	
13/17	HL	CUSHING	OK TV	PAYNE	MATERIAL/WELD/EQUIP FAILURE	THREADED CONNECTION/COUPLING FAILURE	0	0	\$10,799	15	0	\$799 ¢1.130	
24/17 22/17	HL HL	LONGVIEW HEARNE	TX TX	GREGG ROBERTSON	CORROSION INCORRECT OPERATION	INTERNAL OVERFILL/OVERFLOW OF TANK/VESSEL/SUMP	0	0	\$91,120 \$512	20	0	\$1,120 \$12	
22/17 14/17	HL	ANDREWS	TX	ANDREWS	MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT	0	0	\$512 \$545	1	0	\$12 \$45	
08/17	HL	BROWNWOOD	TX	BROWN COUNTY	CORROSION	EXTERNAL	0	0	\$31,023	0	0	\$23	
31/17	HL	POLLAK	TX	ANGELINA	OTHER OUTSIDE FORCE DAMAGE	VEHICLE NOT ENGAGED IN EXCAVATION	0	0	\$74,766	600	100	\$4,766	
6/17	HL	BARNSDALL	ОК	OSAGE	EXCAVATION DAMAGE	THIRD PARTY EXCAVATION DAMAGE	0	0	\$430,000	110	5	\$5,000	
1/17	HL	MORGANTOWN	PA	BERKS	CORROSION	EXTERNAL	0	0	\$338,166	20	20	\$205	
27/17	HL	ROSEDALE	OK	MCCLAIN	EXCAVATION DAMAGE	THIRD PARTY EXCAVATION DAMAGE	0	0	\$73,657	37	5	\$221	
01/17	HL	CORSICANA	TX	NAVARRO	CORROSION	EXTERNAL	0	0	\$45,151	3	3	\$151	
26/17	HL	LIBERTY	TX	LIBERTY	CORROSION	INTERNAL	0	0	\$10,025	0	0	\$25	
13/17	HL	ASTON	PA	DELAWARE	MATERIAL/WELD/EQUIP FAILURE	THREADED CONNECTION/COUPLING FAILURE	0	0	\$39,846	16	0	\$1,546	
10/17	HL	SHARON HILL	PA	DELAWARE	CORROSION	INTERNAL	0	0	\$23,875	1	0	\$0	
20/16	HL	YALE	OK	CREEK	MATERIAL/WELD/EQUIP FAILURE	MANUFACTURING-RELATED	0	0	\$18,750	75	0	\$3,750	
19/16	HL	YALE	OK	CREEK	MATERIAL/WELD/EQUIP FAILURE	MANUFACTURING-RELATED	0	0	\$15,243	5	0	\$243	
6/16	HL	STOWELL CORSICANA	TX TX	CHAMBERS NAVARRO	INCORRECT OPERATION CORROSION	PIPELINE/EQUIPMENT OVERPRESSURED	0	0	\$212	0	0	\$12	
29/16 21/16	HL HL	GAMBLE TOWNSHIP	PA.	LYCOMING	OTHER OUTSIDE FORCE DAMAGE	INTERNAL OTHER OUTSIDE FORCE DAMAGE	0	0	\$2,017 \$2,562,426	1,238	1,238	\$17 \$85,722	
22/16	HL	GOODRICH	TX	POLK	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$19,000	1,230	1,236	\$03,722	
07/16	HL	SOUR LAKE	TX	HARDIN	INCORRECT OPERATION	INCORRECT VALVE POSITION	0	0	\$5,260	3	0	\$60	
9/16	HL	SWEETWATER	TX	NOLAN	CORROSION	EXTERNAL	0	0	\$4,017,900	8,600	6,600	\$354,900	
.6/16	HL	ALLEGHENY TOWNSHIP	PA	BLAIR	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$14,450	5	5	\$150	
5/16	HL	CORSICANA	TX	NAVARRO	MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT	0	0	\$1,114	0	0	\$14	
6/16	HL	TULSA	OK	TULSA	ALL OTHER CAUSES	UNKNOWN	0	0	\$0	0	0	\$0	
5/16	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$773,395	50	10	\$395	
0/16	HL	NEW LONDON	TX	RUSK	CORROSION	EXTERNAL	0	0	\$11,024	0	0	\$24	
05/16	HL	NOME	TX	JEFFERSON	MATERIAL/WELD/EQUIP FAILURE	THREADED CONNECTION/COUPLING FAILURE	0	0	\$1,030	0	0	\$30	
13/16	HL	WINNIE	TX	CHAMBERS	CORROSION	INTERNAL	0	0	\$30,500	0	0	\$0	
6/16	HL	CORSICANA	TX	NAVARRO	CORROSION	EXTERNAL	0	0	\$49,546	1	1	\$46	
27/16	HL	ASTON	PA	DELAWARE	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$7,743	9	9	\$123	
03/16	HL	CENTER	TX	SHELBY	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$7,230	105	0	\$30	
14/16	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$47,020	195 20	20	\$520	
11/16 03/16	HL HL	CHILDRESS CORSICANA	TX TX	CHILDRESS NAVARRO	CORROSION CORROSION	EXTERNAL INTERNAL	0	0	\$368,240 \$42,451	20 4	15 3	\$341 \$101	
20/16	HL	WESTVILLE	NJ	GLOUCESTER	NATURAL FORCE DAMAGE	TEMPERATURE	0	0	\$13,616	1	0	\$101	
	HL	ALVORD	TX	WISE	CORROSION	INTERNAL	0	0	\$44,884	2	1	\$110	
18/15		ALVORD	1.7	WISE			-	-			_		
18/15 18/15	HL	RANGER	TX	EASTLAND	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$12,075	2	2	\$75	

Date	System	City	State	County	Cause	Sub Cause	Fatalities	Injuries	Property Damage (A)	Gross Barrels Spilled (Haz Liq)	Net Barrels Lost (Haz Liq)	Value of Product Lost ^(D)
10/28/15	HL	NOME	TX	JEFFERSON	CORROSION	INTERNAL	0	0	\$274,836	5	3	\$128
10/27/15	HL	NOME	TX	JEFFERSON	CORROSION	INTERNAL	0	0	\$3,000	0	0	\$0
10/15/15	HL	GOODRICH	TX	POLK	CORROSION	INTERNAL	0	0	\$123,584	10	10	\$428
10/13/15	HL HL	HONEYBROOK DIBOLL	PA TX	CHESTER ANGELINA	INCORRECT OPERATION EXCAVATION DAMAGE	INCORRECT VALVE POSITION OPERATOR/CONTRACTOR EXCAVATION DAMAGE	0	0	\$47,892 \$5,026	215 0	0	\$4,892 \$26
09/22/15	HL HL	RANGER	TX	EASTLAND	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$3,585	2	2	\$26 \$85
09/03/15	HL	BEAUMONT	TX	JEFFERSON	OTHER OUTSIDE FORCE DAMAGE	VEHICLE NOT ENGAGED IN EXCAVATION	0	0	\$150,001	0	0	\$1
09/01/15	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$5,045	1	1	\$45
08/21/15	HL	NOME	TX	JEFFERSON	CORROSION	INTERNAL	0	0	\$22,000	1	0	\$0
07/26/15	HL	BEAUMONT	TX	JEFFERSON	MATERIAL/WELD/EQUIP FAILURE	THREADED CONNECTION/COUPLING FAILURE	0	0	\$5,000	1	0	\$0
07/16/15	HL	MAYSVILLE	OK	GARVIN	INCORRECT OPERATION	OVERFILL/OVERFLOW OF TANK/VESSEL/SUMP	0	0	\$2,800	1	0	\$50
07/09/15	HL	CORSICANA	TX	NAVARRO	CORROSION	EXTERNAL OTHER THEODERS OF A TION	0	0	\$41,676	4	4	\$225
06/23/15 06/14/15	HL HL	CORSICANA OREGON	TX OH	NAVARRO LUCAS	INCORRECT OPERATION MATERIAL/WELD/EQUIP FAILURE	OTHER INCORRECT OPERATION DEFECTIVE OR LOOSE TUBING/FITTING	0	0	\$33,022 \$2,540	0	0	\$22 \$20
05/31/15	HL	DIBOLL	TX	ANGELINA	CORROSION	INTERNAL	0	0	\$127.056	60	10	\$568
05/28/15	HL	CORSICANA	TX	NAVARRO	INCORRECT OPERATION	INCORRECT VALVE POSITION	0	0	\$30,163	20	3	\$163
05/12/15	HL	WORTHAM	TX	FREESTON	NATURAL FORCE DAMAGE	LIGHTNING	0	0	\$19,000	0	0	\$0
05/11/15	HL	CORSICANA	TX	NAVARRO	NATURAL FORCE DAMAGE	HEAVY RAINS/FLOODS	0	0	\$2,212,822	650	20	\$1,110
05/08/15	HL	DAYTON	TX	LIBERTY	CORROSION	EXTERNAL	0	0	\$524,139	3	3	\$315
04/20/15	HL	SINKING SPRINGS	PA	BERKS	INCORRECT OPERATION	OTHER INCORRECT OPERATION	0	0	\$530	0	0	\$30
04/10/15 03/26/15	HL HL	GLEN MILLS ASTON	PA PA	DELAWARE DELAWARE	CORROSION MATERIAL/WELD/EQUIP FAILURE	EXTERNAL MALFUNCTION OF CONTROL/RELIEF EQUIPMENT	0	0	\$491,574 \$3,530	0	0	\$24 \$30
03/26/15	HL	WHEELER	TX	WHEELER	MATERIAL/WELD/EQUIP FAILURE	OTHER EQUIPMENT FAILURE	0	0	\$2,550	0	0	\$5 \$5
03/22/15	HL	CUSHING	ОК	PAYNE	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$4,000	8	0	\$0
03/02/15	HL	SHARON HILL	PA	DELAWARE	NATURAL FORCE DAMAGE	TEMPERATURE	0	0	\$41,100	297	0	\$0
03/01/15	HL	ASTON	PA	DELAWARE	MATERIAL/WELD/EQUIP FAILURE	THREADED CONNECTION/COUPLING FAILURE	0	0	\$3,515	0	0	\$15
01/14/15	HL	BEAUMONT	TX	JEFFERSON	MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT	0	0	\$670,000	30	30	\$1,431
11/19/14	HL HL	WHITE OAK HENDERSON	TX TX	GREGG RUSK	INCORRECT OPERATION	INCORRECT INSTALLATION	0	0	\$49,508	1	0	\$50 \$0
11/04/14 11/01/14	HL HL	KINGFISHER	OK	KUSK KINGFISHER	INCORRECT OPERATION MATERIAL/WELD/EQUIP FAILURE	INCORRECT VALVE POSITION MANUFACTURING-RELATED	0	0	\$500 \$424,000	15	0	\$1,000
10/18/14	HL	SOUR LAKE	TX	HARDIN	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$6,538	15	3	\$238
10/09/14	HL	ALEX	ОК	GRADY	CORROSION	INTERNAL	0	0	\$8,082	1	1	\$82
09/25/14	HL	OREGON	ОН	LUCAS	INCORRECT OPERATION	OTHER INCORRECT OPERATION	0	0	\$5,200	1	1	\$100
08/19/14	HL	NEDERLAND	TX	JEFFERSON	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$671	0	0	\$71
05/20/14	HL	EVANT	TX	CORYELL	CORROSION	INTERNAL	0	0	\$47,198	2	2	\$198
04/24/14 04/02/14	HL HL	BEGGS ZEPHYR	OK TX	OKMULGEE BROWN	CORROSION MATERIAL/WELD/EQUIP FAILURE	INTERNAL OTHER EQUIPMENT FAILURE	0	0	\$30,296 \$7,288	3	0	\$296 \$288
03/28/14	HL	ALEX	OK	GRADY	INCORRECT OPERATION	INCORRECT INSTALLATION	0	0	\$1,493	4	0	\$393
03/27/14	HL	CORSICANA	TX	NAVARRO	MATERIAL/WELD/EQUIP FAILURE	DEFECTIVE OR LOOSE TUBING/FITTING	0	0	\$2,000	i	0	\$0
03/14/14	HL	CORSICANA	TX	NAVARRO	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT	0	0	\$2,950	0	0	\$50
03/02/14	HL	CORSICANA	TX	NAVARRO	MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT	0	0	\$3,460	3	0	\$60
02/24/14	HL	LONGVIEW	TX	GREGG	CORROSION	INTERNAL	0	0	\$206,471	20	10	\$1,489
02/21/14	HL	LONGVIEW	TX	GREGG	CORROSION	INTERNAL SATURDS OF SOLVENIENT BOOK	0	0	\$41,885	15	5	\$494
02/18/14 01/22/14	HL HL	WHITE OAK GARY	TX TX	GREGG PANOLA	MATERIAL/WELD/EQUIP FAILURE CORROSION	FAILURE OF EQUIPMENT BODY EXTERNAL	0	0	\$7,000 \$378,368	0 400	0 133	\$0 \$14,356
01/22/14	HL	LONGVIEW	TX	GREGG	CORROSION	INTERNAL	0	0	\$47,741	15	5	\$441
12/28/13	HL	EDMOND	ОК	OKLAHOMA	CORROSION	INTERNAL	0	0	\$336,047	138	97	\$9,312
12/28/13	HL	EDMOND	OK	OKLAHOMA	CORROSION	INTERNAL	0	0	\$39,928	47	33	\$3,193
12/27/13	HL	STOWELL	TX	CHAMBERS	MATERIAL/WELD/EQUIP FAILURE	THREADED CONNECTION/COUPLING FAILURE	0	0	\$478	0	0	\$0
12/20/13	HL	COAL TOWNSHIP	PA	NORTHUMBERLAND	CORROSION MATERIAL (MELD (FOUTD FATURE	EXTERNAL	0	0	\$1,069,253	0	0	\$8
12/05/13 11/30/13	HL HL	CUSHING STOWELL	OK TX	PAYNE CHAMBERS	MATERIAL/WELD/EQUIP FAILURE MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT NON-THREADED CONNECTION FAILURE	0	0	\$9,530 \$1,418	7 0	0	\$0 \$21
11/30/13	HL	EDMOND	OK	OKLAHOMA	CORROSION	INTERNAL	0	0	\$1,416	7	7	\$21 \$632
11/13/13	HL	DIBOLL	TX	ANGELINA	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	ő	0	\$3,450	1	1	\$100
10/05/13	HL	TYLER	TX	SMITH	CORROSION	EXTERNAL	0	0	\$266,257	30	10	\$1,003
09/24/13	HL	TEMPLE	TX	BELL	INCORRECT OPERATION	OTHER INCORRECT OPERATION	0	0	\$45,834	5	5	\$498
09/04/13	HL HI	ALEX	OK PA	GRADY	CORROSION CORROSION	INTERNAL EXTERNAL	0	0	\$200	1 0	0	\$100
08/19/13 08/09/13	HI.	ASTON LIBERTY	TX	DELEWARE COUNTY	CORROSION	INTERNAL	0	0	\$4,620 \$6,553	0	0	\$120 \$53
07/11/13	HL	OREGON	ОН	LUCAS	MATERIAL/WELD/EQUIP FAILURE	CONSTRUCTION, INSTALLATION OR FABRICATION-RELATED	0	0	\$55,540	0	0	\$0
06/25/13	HL	RINGGOLD	TX	MONTAQUE	MATERIAL/WELD/EQUIP FAILURE	DEFECTIVE OR LOOSE TUBING/FITTING	0	0	\$199,740	150	60	\$5,505
05/20/13	HL	UPPER CHICHESTER	PA	DELAWARE	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$45,672	5	0	\$672
05/14/13	HL	KELLER	TX	TARRANT	CORROSION	INTERNAL	0	0	\$13,521	2	0	\$46
05/07/13	HL	SPRING TOWNSHIP	PA	BERKS	CORROSION	EXTERNAL OTHER THEODERS OF A TION	0	0	\$7,661	0	0	\$0
04/23/13	HL HL	CORSICANA	TX TX	NAVARRO NAVARRO	INCORRECT OPERATION	OTHER INCORRECT OPERATION	0	0	\$24,015 \$2,617	4	4	\$343 \$67
04/03/13 03/20/13	HL HI	CORSICANA	TX	NAVARRO	MATERIAL/WELD/EQUIP FAILURE MATERIAL/WELD/EQUIP FAILURE	THREADED CONNECTION/COUPLING FAILURE THREADED CONNECTION/COUPLING FAILURE	0	0	\$2,617 \$133,107	300	140	\$67 \$12,530
03/20/13	HL	MIDLOTHIAN	TX	ELLIS	CORROSION	EXTERNAL	0	0	\$216,515	50	38	\$3,363
03/11/13	HL	DEVERS	TX	LIBERTY	MATERIAL/WELD/EQUIP FAILURE	OTHER EQUIPMENT FAILURE	0	0	\$29,459	37	17	\$1,549
02/28/13	HL	CIMMARON	ОК	LOGAN	CORROSION	INTERNAL	0	0	\$214,538	75	0	\$0
02/23/13	HL	CHESTER	TX	TYLER	CORROSION	INTERNAL	0	0	\$3,634,605	550	50	\$4,488
02/14/13	HL	SOUR LAKE	TX	HARDIN	INCORRECT OPERATION	PIPELINE/EQUIPMENT OVERPRESSURED	0	0	\$38,197	0	0	\$30
02/09/13 02/08/13	HL HI	BRECKENRIDGE CHESTER	TX TX	STEPHENS TYLER	CORROSION CORROSION	INTERNAL INTERNAL	0	0	\$117,898 \$270,046	15 7	13 0	\$1,199 \$46
02,00,13	III.	CILSTER	1.	TILLE	CORROSION	INTERNAL	U	U	\$270,040	,	U	¥+0

Date	System	City	State	County	Cause	Sub Cause	Fatalities	Injuries	Property Damage (A)	Gross Barrels Spilled (Haz Liq)	Net Barrels Lost (Haz Liq)	Value of Product Lost ^(D)
02/07/13	HL	CHESTER	TX	TYLER	CORROSION	INTERNAL	0	0	\$37,089	3	2	\$185
02/06/13	HL	RANGER	TX	STEPHENS	CORROSION	INTERNAL	0	0	\$163,973	25	25	\$2,325
02/05/13	HL	BEAUMONT	TX	JEFFERSON	MATERIAL/WELD/EQUIP FAILURE	THREADED CONNECTION/COUPLING FAILURE	0	0	\$585	0	0	\$45
02/03/13	HL	BRECKENRIDGE	TX	STEPHENS	CORROSION	INTERNAL	0	0	\$115,462	25	25	\$2,356
01/24/13	HL	RANGER	TX	STEPHENS	CORROSION	INTERNAL	0	0	\$734,668	350	230	\$21,275
01/07/13 01/04/13	HL	COLMESNEIL SINKING SPRING	TX PA	TYLER BERKS	MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT MANUFACTURING-RELATED	0	0	\$45,029 \$225,400	10	10	\$897
01/04/13	HL HL	PADACUH	TX	COTTLE	MATERIAL/WELD/EQUIP FAILURE CORROSION	MANUFACTURING-RELATED EXTERNAL	0	0	\$225,400	12 2	0	\$1,400 \$179
12/21/12	HL	WAYNE	MI	WAYNE	INCORRECT OPERATION	OTHER INCORRECT OPERATION	0	0	\$1,216,083	3	0	\$300
12/19/12	HL	RINGGOLD	TX	MONTAGUE	CORROSION	INTERNAL	0	0	\$2,880	1	0	\$80
12/16/12	HL	ASTON	PA	DELEWARE	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$11,000	3	0	\$0
11/12/12	HL	SARATOGA	TX	HARDIN	CORROSION	INTERNAL	0	0	\$12,041	0	0	\$41
10/01/12	HL	WARREN	TX	TYLER	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT	0	0	\$7,024	0	0	\$24
09/26/12	HL	WORTHAM	TX	ROBERTSON	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT	0	0	\$24,598	13	3	\$276
08/19/12	HL	SHARON HILL	PA	DELAWARE	CORROSION	INTERNAL	0	0	\$46,000	4	0	\$0
08/15/12 08/03/12	HL HL	SOUR LAKE SOUR LAKE	TX TX	HARDIN HARDIN	CORROSION CORROSION	EXTERNAL INTERNAL	0	0	\$12,453	3	3	\$300 \$40
08/03/12	HL HL	SOUR LAKE KURTEN	TX	BRAZOS	CORROSION	INTERNAL EXTERNAL	0	0	\$5,040 \$18,000	0	0	\$40 \$0
07/12/12	HL	KURTEN	TX	BRAZOS	CORROSION	EXTERNAL	0	0	\$18,162	2	2	\$162
07/06/12	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$1,137	0	0	\$12
06/20/12	HL	LONGVIEW	TX	GREGG	CORROSION	INTERNAL	0	0	\$2,909	0	0	\$9
05/18/12	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$10,454	10	2	\$176
05/14/12	HL	BIG SPRING	TX	HOWARD	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT	0	0	\$4,020	0	0	\$20
05/10/12	HL	CHILDRESS	TX	CHILDRESS	CORROSION	EXTERNAL	0	0	\$259,533	20	20	\$1,870
04/08/12	HL	SOUR LAKE	TX	HARDIN	INCORRECT OPERATION	OVERFILL/OVERFLOW OF TANK/VESSEL/SUMP	0	0	\$25,060	5	5	\$500
04/02/12	HL	HEARNE	TX	ROBERTSON	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT	0	0	\$1,800	4	0	\$0 +50
03/06/12	HL HL	STOWELL	TX TX	CHAMBERS LIBERTY	CORROSION CORROSION	INTERNAL INTERNAL	0	0	\$18,160	0	0	\$50 \$12
03/02/12 02/27/12	HL HL	MAYSVILLE	OK	GARVIN	CORROSION	INTERNAL	0	0	\$15,012 \$4,253	2	0	\$12 \$53
02/09/12	HL	WHITE OAK	TX	GREGG	INCORRECT OPERATION	INCORRECT INSTALLATION	0	0	\$2,034	0	0	\$34
01/12/12	HL	WELLINGTON	OH	LORRAIN	EXCAVATION DAMAGE	PREVIOUS DAMAGE DUE TO EXCAVATION	0	0	\$17,904,594	1,950	1,221	\$3,289
01/11/12	HL	HULL	TX	LIBERTY	CORROSION	INTERNAL	0	0	\$23,129	2	2	\$292
01/06/12	HL	ROBERT LEE	TX	COKE	CORROSION	INTERNAL	0	0	\$89,622	117	117	\$11,466
12/29/11	HL	HAWLEY	TX	JONES	MATERIAL/WELD/EQUIP FAILURE	OTHER EQUIPMENT FAILURE	0	0	\$3,612	2	2	\$192
12/20/11	HL	SARATOGA	TX	HARDIN	INCORRECT OPERATION	OVERFILL/OVERFLOW OF TANK/VESSEL/SUMP	0	0	\$5,434	2	2	\$242
12/11/11	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$7,696	0	0	\$96
12/01/11	HL	RULE	TX	HASKELL	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT	0	0	\$4,185	0	0	\$35
11/02/11 10/13/11	HL HL	BIG SPRING TEMPLE	TX TX	HOWARD BELL	MATERIAL/WELD/EQUIP FAILURE MATERIAL/WELD/EQUIP FAILURE	DEFECTIVE OR LOOSE TUBING/FITTING NON-THREADED CONNECTION FAILURE	0	0	\$45 \$10	0	0	\$45 \$10
10/13/11	HL	TULSA	OK	TULSA	CORROSION	INTERNAL	0	0	\$12,257	25	0	\$10 \$0
10/04/11	HL	SOUR LAKE	TX	HARDIN	CORROSION	INTERNAL	0	0	\$3,308	0	0	\$36
09/26/11	HL	ASTON	PA	PA	OTHER OUTSIDE FORCE DAMAGE	OTHER OUTSIDE FORCE DAMAGE	0	0	\$365,591	78	0	\$0
08/31/11	HL	PRICE	TX	RUSK	CORROSION	INTERNAL	0	0	\$10,904	2	2	\$171
08/29/11	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$27,598	4	3	\$251
07/22/11	HL	DIBOLL	TX	ANGELINA	INCORRECT OPERATION	PIPELINE/EQUIPMENT OVERPRESSURED	0	0	\$3,575	1	1	\$144
04/27/11	HL	RINGGOLD	TX	MONTAGUE	CORROSION	INTERNAL	0	0	\$49,832	8	2	\$219
04/19/11	HL	LONGVIEW	TX	GREGG	MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT	0	0	\$1,414	1	1	\$105
02/14/11	HL	WYNNEWOOD	OK	MURRAY	CORROSION	INTERNAL	0	0	\$67,021	78	58	\$4,713
02/13/11 02/12/11	HL HL	DIBOLL WHITE OAK	TX TX	ANGELINA GREGG	INCORRECT OPERATION CORROSION	OVERFILL/OVERFLOW OF TANK/VESSEL/SUMP EXTERNAL	0	0	\$5,769 \$126,058	4 40	1 16	\$83 \$1,312
02/12/11	HL	LONGVIEW	TX	GREGG	MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT	0	0	\$120,038	0	0	\$1,312 \$42
02/08/11	HL	SHARON HILL	PA	DELAWARE	CORROSION	INTERNAL	0	0	\$257,250	38	0	\$0
01/19/11	HL	MAYSVILLE	OK	GARVIN	CORROSION	INTERNAL	0	0	\$816,730	1,250	1,035	\$90,304
01/03/11	HL	PAMPA	TX	GRAY	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT	0	0	\$2,555	0	0	\$44
12/04/10	HL	LIVINGSTON	TX	POLK	CORROSION	INTERNAL	0	0	\$155,340	75	45	\$3,825
11/20/10	HL	NEW WAVERLY	TX	WALKER	MATERIAL/WELD/EQUIP FAILURE	CONSTRUCTION, INSTALLATION OR FABRICATION-RELATED	0	0	\$438,060	100	100	\$8,500
11/15/10	HL	DIBOLL	TX OK	ANGELINE	INCORRECT OPERATION	OVERFILL/OVERFLOW OF TANK/VESSEL/SUMP	0	0	\$19,434	15 0	5	\$405
11/12/10	HL HI	ENID ST. CLAIR	OK MT	GARFIELD ST. CLAIR	INCORRECT OPERATION CORROSION	INCORRECT VALVE POSITION EXTERNAL	0	0	\$7,368 \$75,000	0	0	\$40 \$0
09/30/10	HI.	THOMAS	TX	GREGG	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$75,000	1	1	\$0 \$77
09/30/10	HL	BEAUMONT	TX	JEFFERSON	EXCAVATION DAMAGE	OPERATOR/CONTRACTOR EXCAVATION DAMAGE	0	0	\$3,982 \$1,020	0	0	\$20
09/27/10	HL	BEAUMONT	TX	JEFFERSON	INCORRECT OPERATION	INCORRECT VALVE POSITION	0	0	\$8,913	1	0	\$0
09/24/10	HL	BRECKENRIDGE	TX	STEPHENS	INCORRECT OPERATION	OVERFILL/OVERFLOW OF TANK/VESSEL/SUMP	0	0	\$237	2	1	\$37
09/16/10	HL	ANSON	TX	JONES	MATERIAL/WELD/EQUIP FAILURE	CONSTRUCTION, INSTALLATION OR FABRICATION-RELATED	0	0	\$18,865	0	0	\$35
08/22/10	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$398,039	100	98	\$6,860
07/31/10	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$19,227	3	2	\$227
07/11/10	HL	THOMAS	TX	GREGG	CORROSION	EXTERNAL	0	0	\$43,361	6	6	\$414
07/04/10	HL	DRUMRIGHT	OK	CREEK	CORROSION	INTERNAL	0	0	\$29,411	1	0	\$69
06/16/10 06/10/10	HL HL	COLMESNEIL DOUGLAS	TX	TYLER NACOGDOCHES	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT PUMP OR PUMP-RELATED EOUIPMENT	0	0	\$5,011 \$2,536	0	0	\$11 ¢36
06/10/10	HL HL	HOUSTON	TX TX	NACOGDOCHES HARRIS	MATERIAL/WELD/EQUIP FAILURE MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT	0	0	\$2,536 \$16,534	3	3	\$36 \$0
05/27/10	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$9,499	0	0	\$30
05/19/10	HL	LONGVIEW	TX	GREGG	MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT	0	0	\$6,868	1	1	\$67
04/10/10	HL	CASHION	ОК	LOGAN COUNTY	MATERIAL/WELD/EQUIP FAILURE	CONSTRUCTION, INSTALLATION OR FABRICATION-RELATED	0	0	\$167,904	0	0	\$2
T II												

Date	System	City	State	County	Cause	Sub Cause	Fatalities	Injuries	Property Damage (A)	Gross Barrels Spilled (Haz Liq)	Net Barrels Lost (Haz Liq)	Value of Product Lost ^(D)
04/05/10	HL	PHAROAH	ок	OKFUSKEE	MATERIAL/WELD/EQUIP FAILURE	PUMP OR PUMP-RELATED EQUIPMENT	0	0	\$7,815	3	0	\$249
03/15/10	HL	WHITE OAK	TX	GREGG	MATERIAL/WELD/EQUIP FAILURE	MALFUNCTION OF CONTROL/RELIEF EQUIPMENT	0	0	\$11,497	0	0	\$46
03/15/10	HL	COMYN	TX	COMANCHE	MATERIAL/WELD/EQUIP FAILURE	NON-THREADED CONNECTION FAILURE	0	0	\$765	0	0	\$10
03/09/10	HL	LONGVIEW	TX	GREGG	MATERIAL/WELD/EQUIP FAILURE	THREADED CONNECTION/COUPLING FAILURE	0	0	\$5,039	1	0	\$39
03/09/10	HL	CORSICANA	TX	NAVARRO	MATERIAL/WELD/EQUIP FAILURE	CONSTRUCTION, INSTALLATION OR FABRICATION-RELATED	0	0	\$26,064	1	0	\$78
02/20/10 12/31/09	HL HL	LONGVIEW LONGVIEW	TX TX	GREGG GREGG	MATERIAL/WELD/EQUIP FAILURE	OTHER EQUIPMENT FAILURE	0	0	\$93,513 \$500	8	2	\$152
12/31/09	III.	CORSICANA	TX	NAVARRO	MATERIAL/WELD/EQUIP FAILURE INCORRECT OPERATION	UNSPECIFIED EQUIPMENT FAILURE INCORRECT OPERATION	0	0	\$16,299	103	0 14	\$0 \$994
12/17/09	HL	PORT ARTHUR	TX	JEFFERSON	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$2,533	0	0	\$33
11/24/09	HL	CORSICANA	TX	NAVARRO	INCORRECT OPERATION	INCORRECT OPERATION	0	0	\$18,378	8	6	\$444
11/19/09	HL	CORSICANA	TX	NAVARRO	CORROSION	UNSPECIFIED CORROSION	0	0	\$28,553	0	0	\$35
11/05/09	HL	KILGORE	TX	GREGG	INCORRECT OPERATION	UNSPECIFIED INCORRECT OPERATION	0	0	\$1,000	2	0	\$0
10/09/09	HL	LONGVIEW	TX	GREGG	NATURAL FORCE DAMAGE	HEAVY RAINS/FLOODS	0	0	\$31,500	2	1	\$65
09/16/09	HL	TIFFIN	OH	SENECA	EXCAVATION DAMAGE	THIRD PARTY EXCAVATION DAMAGE	0	0	\$505,799	671	163	\$52,100
09/02/09	HL	LONGVIEW MONT BELVIEU	TX	GREGG	CORROSION	UNSPECIFIED CORROSION INTERNAL	0	0	\$15,000	4	0	\$0 \$96.780
08/24/09 08/17/09	HL HL	MONT BELVIEU	TX OK	CHAMBERS GARFIELD	CORROSION	INTERNAL UNSPECIFIED CORROSION	0	0	\$529,003 \$5,067	2,500	1,613 1	\$96,780 \$67
08/03/09	HL	BEAUMONT	TX	JEFFERSON	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$1,500	1	0	\$07
07/05/09	HL	CORSICANA	TX	NAVARRO	CORROSION	UNSPECIFIED CORROSION	0	0	\$17,560	2	2	\$120
05/31/09	HL	LONGVIEW	TX	GREGG	CORROSION	UNSPECIFIED CORROSION	0	0	\$13,158	3	3	\$165
05/29/09	HL	LONGVIEW	TX	GREGG	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$5,116	1	1	\$55
05/08/09	HL	ASTON	PA	DELAWARE	MATERIAL/WELD/EQUIP FAILURE	RUPTURED OR LEAKING SEAL/PUMP PACKING	0	0	\$337,398	59	0	\$5,575
05/04/09	HL	LONGVIEW	TX	GREGG	MATERIAL/WELD/EQUIP FAILURE	RUPTURED OR LEAKING SEAL/PUMP PACKING	0	0	\$44,966	248	2	\$110
05/01/09	HL	COMYN	TX	COMANCHE	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$7,555	4	1	\$55
04/30/09	HL	VALLEY MILLS	TX	BOSQUE	CORROSION	EXTERNAL	0	0	\$28,190	20	15	\$690
04/24/09 03/16/09	HL HL	ASTON LORENA	PA TX	DELAWARE MCLENNAN	INCORRECT OPERATION CORROSION	UNSPECIFIED INCORRECT OPERATION INTERNAL	0	0	\$5,125 \$653,593	1,400	0 730	\$25 \$38,000
03/16/09	III.	LONGVIEW	TX	GREGG	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$053,593	1,400	730	\$38,000
01/17/09	HL	CUSHING	OK	PAYNE	CORROSION	INTERNAL	0	0	\$13,794	10	5	\$190
12/30/08	HL	COLUMBUS	MI	ST. CLAIR	MATERIAL/WELD/EQUIP FAILURE	BUTT WELD	0	0	\$198,979	30	9	\$2,000
12/17/08	HL	LINDEN	NJ	UNION	CORROSION	EXTERNAL	0	0	\$71,550	0	0	\$50
12/05/08	HL	MARYSVILLE	MI	ST. CLAIR	CORROSION	INTERNAL	0	0	\$84,420	10	3	\$420
11/25/08	HL	MURRYSVILLE	PA	WESTMORELAND	INCORRECT OPERATION	INCORRECT OPERATION	0	0	\$1,124,000	280	160	\$14,000
11/17/08	HL	CORSICANA	TX	NAVARRO	CORROSION	INTERNAL	0	0	\$20,300	15	5	\$300
09/23/08 08/04/08	HL HL	KILGORE LONGVIEW	TX TX	GREGG GREGG	CORROSION CORROSION	UNSPECIFIED CORROSION INTERNAL	0	0	\$27,451 \$9,392	1	1	\$100 \$113
07/17/08	HL	ENID	OK	GARFIELD	MATERIAL/WELD/EQUIP FAILURE	THREADS STRIPPED, BROKEN PIPE COUPLING	0	0	\$9,392	5	5	\$113
06/26/08	HL	CLEVELAND	TX	SAN JACINTO	MATERIAL/WELD/EQUIP FAILURE	FILLET WELD	0	0	\$197,601	15	2	\$262
06/11/08	HL	CORSICANA	TX	NAVARRO	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$4,524	4	4	\$524
05/28/08	HL	MCGREGOR	TX	MCLENNAN	INCORRECT OPERATION	UNSPECIFIED INCORRECT OPERATION	0	0	\$500	0	0	\$0
05/07/08	HL	DAISETTA	TX	HARDIN	NATURAL FORCE DAMAGE	EARTH MOVEMENT	0	0	\$100,069	10	10	\$1,120
05/03/08	HL	ENID	OK	GARFIELD	INCORRECT OPERATION	UNSPECIFIED INCORRECT OPERATION	0	0	\$30,036	4	1	\$122
04/25/08	HL	ASTON	PA	DELAWARE	INCORRECT OPERATION	INCORRECT OPERATION	0	0	\$14,500	10	1	\$0
04/22/08	HL HL	SOUR LAKE LONGVIEW	TX TX	HARDIN	CORROSION	INTERNAL	0	0	\$24,050	20	2	\$250 \$50
04/09/08 03/31/08	HL HL	CORSICANA	TX	GREGG NAVARRO	MATERIAL/WELD/EQUIP FAILURE CORROSION	UNSPECIFIED EQUIPMENT FAILURE INTERNAL	0	0	\$850 \$30,000	2 100	1 50	\$5,000
03/16/08	HL	PHILADELPHIA	PA	PHILADELPHIA	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$18,000	100	0	\$100
03/13/08	HL	DIBOLL	TX	ANGELINA	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED MATERIAL/WELD FAILURE	0	0	\$9,567	0	0	\$50
03/04/08	HL	DRUMRIGHT	OK	CREEK	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$525	0	0	\$25
02/07/08	HL	PAULSBORO	NJ	GLOUCESTER	INCORRECT OPERATION	INCORRECT OPERATION	0	0	\$12,550	12	0	\$1,250
01/22/08	HL	MCGREGOR	TX	MCLENNAN	INCORRECT OPERATION	UNSPECIFIED INCORRECT OPERATION	0	0	\$589	1	1	\$89
01/05/08	HL	DIBOLL	TX	ANGELINA	MATERIAL/WELD/EQUIP FAILURE	JOINT/FITTING/COMPONENT	0	0	\$263,186	50	1	\$86
12/20/07 11/19/07	HL HL	FAIRVIEW LONGVIEW	TX TX	WISE GREGG	CORROSION CORROSION	INTERNAL INTERNAL	0	0	\$108,842 \$202,168	2 75	2 5	\$176 \$440
11/19/07	HL HI	NEDERI AND	TX	GREGG IEFFERSON	OTHER OUTSIDE FORCE DAMAGE	INTERNAL INTENTIONAL DAMAGE	0	0	\$202,168 \$62,400	75 30	30	\$440 \$2,400
10/18/07	HL	BEGGS	OK	OKMULGEE	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$62,400	0	0	\$2,400 \$20
09/26/07	HL	CUSHING	OK	PAYNE	CORROSION	INTERNAL	0	0	\$8,070	20	1	\$70
09/14/07	HL	WELLS	TX	ANGELINA	CORROSION	EXTERNAL	0	0	\$192,470	30	7	\$504
08/27/07	HL	RANGER	TX	EASTLAND	CORROSION	UNSPECIFIED CORROSION	0	0	\$6,150	3	2	\$150
08/05/07	HL	LUNA PIER	MI	MONROE	INCORRECT OPERATION	INCORRECT OPERATION	0	0	\$12,800	5	0	\$500
06/27/07	HL	ELMORE CITY	OK	GARVIN	OTHER OUTSIDE FORCE DAMAGE	INTENTIONAL DAMAGE	0	0	\$48,000	50	15	\$1,000
06/20/07	HL	LIVINGSTON	TX TX	POLK NAVARRO	EXCAVATION DAMAGE	THIRD PARTY EXCAVATION DAMAGE UNSPECIFIED CORROSION	0	0	\$121,750	100	10	\$750
06/18/07 06/14/07	HL HL	CORSICANA CUSHING	TX OK	NAVARRO PAYNE	CORROSION CORROSION	UNSPECIFIED CORROSION INTERNAL	0	0	\$5,000 \$107,700	4 25	0 15	\$0 \$1,700
06/14/07	HL HL	CORSICANA	TX	NAVARRO	MATERIAL/WELD/EQUIP FAILURE	INTERNAL UNSPECIFIED EQUIPMENT FAILURE	0	0	\$107,700	25 1	0	\$1,700
05/21/07	HL	ARLINGTON	TX	TARRANT	EXCAVATION DAMAGE	UNSPECIFIED EXCAVATION DAMAGE	0	0	\$42,040	0	0	\$40
05/16/07	HL	SHAMOKIN	PA	NORTHUMBERLAND	EXCAVATION DAMAGE	THIRD PARTY EXCAVATION DAMAGE	0	1	\$2,826,000	1,502	1,287	\$147,000
04/15/07	HL	SINKING SPRING	PA	BERKS	CORROSION	EXTERNAL	0	0	\$20,650	7	0	\$650
04/02/07	HL	HAWLEY	TX	JONES	CORROSION	INTERNAL	0	0	\$31,240	285	20	\$1,240
03/16/07	HL	LONGVIEW	TX	GREGG	CORROSION	UNSPECIFIED CORROSION	0	0	\$35,100	0	0	\$1
02/26/07	HL	TAYLOR	MI	WAYNE	NATURAL FORCE DAMAGE	UNSPECIFIED NATURAL FORCE DAMAGE	0	0	\$2,300	3	1	\$300
02/24/07 02/18/07	HL HL	TULSA SHARON HILL	OK PA	TULSA DELAWARE	MATERIAL/WELD/EQUIP FAILURE	RUPTURED OR LEAKING SEAL/PUMP PACKING UNSPECIFIED EQUIPMENT FAILURE	0	0	\$15,060 \$3,060	12 0	1	\$60 \$60
02/18/07	HL HI	SHARON HILL ALVORD	PA TX	DELAWARE	MATERIAL/WELD/EQUIP FAILURE CORROSION	UNSPECIFIED EQUIPMENT FAILURE UNSPECIFIED CORROSION	0	0	\$3,060 \$500	0	0	\$60 \$0
02,10,07	116	ALVORD	1/	WISL	CORROSION	SNSI ECII IED CORROSION	0	U	\$300	4	0	40

Date	System	City	State	County	Cause	Sub Cause	Fatalities	Injuries	Property Damage (A)	Gross Barrels Spilled (Haz Liq)	Net Barrels Lost (Haz Liq)	Value of Product Lost ^(D)	
02/07/07	HL	ROMULUS	MI	WAYNE	NATURAL FORCE DAMAGE	TEMPERATURE	0	0	\$30,000	14	1	\$1,200	
02/06/07	HL	ARLINGTON	TX	TARRANT	EXCAVATION DAMAGE	THIRD PARTY EXCAVATION DAMAGE	0	0	\$571,294	518	94	\$5,640	
01/29/07	HL	CORSICANA	TX	NAVARRO	CORROSION	UNSPECIFIED CORROSION	0	0	\$8,120	2	0	\$120	
12/27/06	HL	SYLVANIA	PA	BRADFORD	MATERIAL/WELD/EQUIP FAILURE	RUPTURED OR LEAKING SEAL/PUMP PACKING	0	0	\$6,000	0	0	\$0	
12/15/06	HL	BRONTE	TX	COKE	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED MATERIAL/WELD FAILURE	0	0	\$6,700	4	4	\$200	
12/04/06	HL	CHILTON	TX	FALLS	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$2,100	3	0	\$0	
11/14/06	HL	MARYSVILLE	MI	ST. CLAIR	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$6,100	0	0	\$100	
11/09/06	HL	KILGORE	TX	GREGG	EXCAVATION DAMAGE	THIRD PARTY EXCAVATION DAMAGE	0	0	\$136,000	350	20	\$18,000	
10/05/06	HL	ASTON	PA	DELAWARE	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$10,000	0	0	\$50	
09/26/06	HL	TOLEDO	OH	LUCAS	MATERIAL/WELD/EQUIP FAILURE	JOINT/FITTING/COMPONENT	0	0	\$54,020	0	0	\$20	
09/06/06	HL	KILGORE	TX	GREGG	CORROSION	UNSPECIFIED CORROSION	0	0	\$415	0	0	\$0	
08/29/06	HL	NEWARK	NJ	ESSEX	CORROSION	EXTERNAL	0	0	\$101,725	19	0	\$2,000	
08/21/06	HL	HAWLEY	TX	JONES	CORROSION	INTERNAL	0	0	\$49,920	100	65	\$4,420	
08/13/06	HL	TULSA	OK	TULSA	ALL OTHER CAUSES	UNKNOWN	0	0	\$2,350	2	1	\$100	
07/17/06	HL	CUSHING	OK	PAYNE	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$1,285	0	0	\$35	
06/19/06	HL	TYE	TX	TAYLOR	CORROSION	INTERNAL	0	0	\$183,000	500	333	\$30,000	
06/15/06	HL	SEMINOLE	OK	SEMINOLE	EXCAVATION DAMAGE	THIRD PARTY EXCAVATION DAMAGE	0	0	\$4,200	200	0	\$0	
05/31/06	HL	DUBLIN	TX	ERATH	CORROSION	EXTERNAL	0	0	\$38,725	15	15	\$725	
05/31/06	HL	DUBLIN	TX	ERATH	CORROSION	EXTERNAL	0	0	\$23,725	10	10	\$725	
05/04/06	HL	CORSICANA	TX	NAVARRO	CORROSION	UNSPECIFIED CORROSION	0	0	\$2,350	3	3	\$150	
05/01/06	HL	HAWLEY	TX	JONES	CORROSION	INTERNAL	0	0	\$12,200	15	10	\$500	
04/29/06	HL	TULSA	OK	TULSA	CORROSION	INTERNAL	0	0	\$25,698	63	3	\$698	
04/25/06	HL	ALANREED	TX	DONLEY	CORROSION	EXTERNAL	0	0	\$18,000	15	5	\$300	
04/03/06	HL	CORSICANA	TX	NAVARRO	INCORRECT OPERATION	UNSPECIFIED INCORRECT OPERATION	0	0	\$525	0	0	\$25	
03/21/06	HL	KELLER	TX	TARRANT	NATURAL FORCE DAMAGE	UNSPECIFIED NATURAL FORCE DAMAGE	0	0	\$1,006	0	0	\$6	
03/20/06	HL	RINGGOLD	TX	MONTAGUE	MATERIAL/WELD/EQUIP FAILURE	UNSPECIFIED EQUIPMENT FAILURE	0	0	\$1,525	0	0	\$25	
03/09/06	HL	TAYLOR	MI	WAYNE	NATURAL FORCE DAMAGE	UNSPECIFIED NATURAL FORCE DAMAGE	0	0	\$1,510	0	0	\$10	
02/24/06	HL		TX	EASTLAND	CORROSION	INTERNAL	0	0	\$34,100	10	10	\$600	
02/24/06	HL		TX	EASTLAND	CORROSION	INTERNAL	0	0	\$44,100	35	35	\$2,100	
02/21/06	HL		TX	EASTLAND	CORROSION	INTERNAL	0	0	\$95,000	75	30	\$18,000	
01/07/06	HL	TOLEDO	ОН	LUCAS	CORROSION	EXTERNAL	0	0	\$94,900	1	0	\$200	
Totals							0	1	\$56,652,909	28,497	16,697	\$1,167,240	

- A For years 2002 and later, property damage is estimated as the sum of all public and private costs reported in the 30-day incident report. All costs shown are as reported by the operator at the time of the incident.

 3. Starting Sept 2013, this column displays "volume released unintentionally" for all years after 2009. Before Sept 2013, the column displayed the sum of "volume released unintentionally" and "volume released intentionally" for all years after 2009.

 3. Net Barrels Lost applies only to Liquid incidents and is the difference between Gross Barrels Spilled and Barrels Recovered.

 3. Value of product lost is the estimated value of the released product at the time the report was made.

- Operator specifics are obtained from self-reported annual reports since 2006. Unless otherwise noted, the most recently submitted report is used as the basis for the information here. Raw data files are available from the PHMSA Data and Statistics page. Please note that PHMSA's Office of Pipeline Safety is continually checking the quality and accuracy of these reports, therefore that a presented here may change as we receive supplementary information from operators. Ascertainment date: February 1, 2018.

 PHMSA Flagged Indents Fig. 2018. Note: Indicates occurring up to all one yet present of the properties of the prop

For comments and questions on the information presented on this site, please send us feedback.